

	Type	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1	13029	(water near3 (measur\$ or monitor\$) and (automat\$ or (self near1 calibrat\$)))	USPAT; EPO; JPO; DERWENT	2003/09/29 20:42
2	BRS	L2	2942	(water near3 (measur\$ or monitor\$) and (automat\$ or (self near1 calibrat\$)))	EPO; JPO; DERWENT	2003/09/29 20:53
3	BRS	L3	7	2 and (ion near1 (sensitive or selective))	EPO; JPO; DERWENT	2003/09/29 20:53
4	BRS	L4	32	2 and probes	EPO; JPO; DERWENT	2003/09/29 20:46
5	BRS	L5	32	4 not 3	USPAT; EPO; JPO; DERWENT	2003/09/29 20:46
6	BRS	L6	838	(water near2 (quality)) and (automat\$ or (self near1 calibrat\$))	EPO; JPO; DERWENT	2003/09/29 21:05
7	BRS	L7	0	6 and (ion near1 (sensitive or selective))	EPO; JPO; DERWENT	2003/09/29 20:54
8	BRS	L8	52	6 and (electrode or probe)	EPO; JPO; DERWENT	2003/09/29 20:54
9	BRS	L9	47	8 not 5	EPO; JPO; DERWENT	2003/09/29 20:54
10	BRS	L10	2708	(water near2 (quality or monitor\$ or measur\$)) and (automat\$ or (self near1 calibrat\$))	EPO; JPO; DERWENT	2003/09/29 21:06
11	BRS	L11	2713	(water near2 (quality or monitor\$ or measur\$)) and (automat\$ or (self near1 (calibrat\$ or test\$)))	EPO; JPO; DERWENT	2003/09/29 21:08

	Type	L #	Hits	Search Text	DBs	Time Stamp
12	BRS	L12	3	11 and (gas near1 purge)	EPO; JPO; DERWEN T	2003/09/29 21:08
13	BRS	L13	0	11 and (nitrogen near1 purge)	EPO; JPO; DERWEN T	2003/09/29 21:08
14	BRS	L14	1466	(water near2 (quality or monitor\$ or measur\$)).ab.	USPAT	2003/09/29 21:43
15	BRS	L15	322	14 and (electrodes or probes)	USPAT	2003/09/29 21:26